


Engels et al., 2006 - Figure 9 - Fragment of a chirp-sonar subbottom record west of the study area (SCICEX-98; see Figure 1 for location) illustrating iceberg scouring to water depths of between 350-400 m and truncation of the inclined bedrock strata on the slope, with an erosional bench between 450-500 m.