

2011.05.22

UTC

0730L arrive ACO site

Home beacon on bottom per Jason is  
going down on Jason

#41  
#61

wrong - 43  
float dive/  
recovery

Reminded Matt about practicing mate - demate

0825L Both medea and Jason in water

J2-552

Jason dive #

1100L 22 May

2100 UTC

2102 on bottom 4724m

trouble w/ USBL

4688 JASON USBL 4724 PRESSURE

4657 MEDEA USBL 39m MEDEA/JASON

31

2129 LBL ANCHOR - WIRES

2140 ANOTHER LBL ANCHOR

2201 SONAR TARGET NOW 30m @ 330

2202 TERMINATION IN SIGHT

still white aragonite - some

DVL work well


Sonar picked up termination/float at ~40m

Home beam 61 working 41 did not work



only stbd arm working  
(port of F)

too hard - wait for 2 arms.  
bring up to replace  
move baseline



on frame in holster - has pin protecting during

See old grip + oval ring

