



**Sea-Bird Electronics, Inc.**  
 13431 NE 20th Street  
 Bellevue, WA 98005 United States

Phone  
 Fax

+1-425-643-9866  
 +1-425-643-9954  
 www.seabird.com

**SERVICE REPORT**

**Service Request**  
**Date**  
**Sales Order**

**1005502978**  
 06-DEC-2017  
 314827994

**CUSTOMER INFORMATION**

Name: KONGSBERG UNDERWATER TECHNOLOGY INC  
 Account : 40280537  
 RICHARD HILE  
 richard.hile@kongsberg.com  
 (425) 245-0557

PO Number:

**Bill To Address**

19210 33RD AVE W;SUITE A;  
 LYNNWOOD,WA,98036,US

**Ship To Address**

19210 33RD AVE W;SUITE A;  
 LYNNWOOD,WA,98036,US

**PRODUCT INFORMATION**

**Item:** APL-GLIDER.LEGACY  
**Item Description:** (LEGACY) APL Glider  
**Serial:** 0273

**Special Notes**

Services Requested:  
 Evaluate/Repair Instrumentation.  
 Perform Routine Calibration Service.

**Problems Found:**

The temperature probe was found to have an intermittent resistance, due to the leads being twisted.

**Services Performed:**

Perform initial diagnostic evaluation.  
 Replaced temperature probe.  
 Replaced the O-rings.  
 Performed a hydrostatic pressure test.  
 Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_SEAGLIDER	Calibrate Seaglider conductivity and temperature sensors	1
CNCRTSEAGLDR	Confirm & Re-certify Webb SLOCUM Glider CTD	1

**Unbilled Items**

Item	Item Description	Qty
802134	VM GLIDER THERM PROBE ASSY,V3,SHIELDED,FENWAL	1
REPGLIDERPROB	Replace SBE Glider thermistor probe	1



**Sea-Bird Electronics, Inc.**  
 13431 NE 20th Street  
 Bellevue, WA 98005 United States

Phone  
 Fax

+1-425-643-9866  
 +1-425-643-9954  
 www.seabird.com

**SERVICE REPORT**

**Service Request**  
**Date**  
**Sales Order**

**1005502978**  
 06-DEC-2017  
 314827994

**PRODUCT INFORMATION**

**Item:** 43F.1113  
**Item Description:** SBE43F, 1/2 MIL, 600m, 3 PIN, GLIDER PLENUM  
**Serial:** 43-3327

**Special Notes**

Services Requested:  
 Evaluate/Repair Instrumentation.  
 Perform Routine Calibration Service.

Services Performed:  
 Perform initial diagnostic evaluation.  
 Performed "POST" cruise calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1

**Unbilled Items**

Item	Item Description	Qty